

## Sweat Solder Kits

### SWEAT SOLDER KITS

| Item No.       | Code No.       | Part No. | Description                                                            |
|----------------|----------------|----------|------------------------------------------------------------------------|
| <b>H-533-A</b> |                |          |                                                                        |
| 1              | <b>3308603</b> | H-532    | 1" Adapter*                                                            |
| 1, 2, 5        | <b>3308780</b> | H-533-AS | Sweat Solder Kit W/Stamped Wall Flange for 1" Supply-Closet & Urinal   |
| 1-4            | <b>3308794</b> | H-533-AC | Sweat Solder Kit W/Cast Wall Flange for 1" Supply-Closet & Urinal      |
| 2              | —              | H-534    | Casing Tube for 1" Copper                                              |
| <b>H-534-A</b> |                |          |                                                                        |
| 1              | <b>3308603</b> | H-532    | 1" Adapter*                                                            |
| 1, 2, 5        | <b>3308783</b> | H-534-AS | Sweat Solder Kit W/Stamped Wall Flange for 1" Supply-Closet & Urinal   |
| 1-4            | <b>3308796</b> | H-534-AC | Sweat Solder Kit W/Cast Wall Flange for 1" Supply-Closet & Urinal      |
| 2              | —              | H-534    | Casing Tube for 1" Copper                                              |
| <b>H-536-A</b> |                |          |                                                                        |
| 1              | <b>3308607</b> | H-535-A  | 3/4" Adapter*                                                          |
| 1, 2, 5        | <b>3308786</b> | H-536-AS | Sweat Solder Kit W/Stamped Wall Flange for 3/4" Supply-Closet & Urinal |
| 1-4            | <b>3308798</b> | H-536-AC | Sweat Solder Kit W/Cast Wall Flange for 3/4" Supply-Closet & Urinal    |
| 2              | —              | H-537    | Casing Tube for 3/4" Copper                                            |

Note: H-532-AS, H-533-AS, H-534-AS, H-535-AS and H-536-AS are also identified as suffix YB when furnished with flush valve.

\*Furnished separate for concealed installations.

| Item No.        | Code No.       | Part No. | Description                                     |
|-----------------|----------------|----------|-------------------------------------------------|
| <b>H-633-AA</b> |                |          |                                                 |
| 1               | <b>3308603</b> | H-532    | 1" Adapter                                      |
| 1-4             | <b>3308782</b> | H-633-AA | Sweat Solder Kit for 1" Supply – Urinal 3" Tube |
| 2               | —              | H-534    | Casing Tube for 1" Copper                       |
| <b>H-634-AA</b> |                |          |                                                 |
| 1               | <b>3308603</b> | H-532    | 1" Adapter                                      |
| 1-4             | <b>3308785</b> | H-634-AA | Sweat Solder Kit for 1" Supply – Closet 6" Tube |
| 2               | —              | H-534    | Casing Tube for 1" Copper                       |
| <b>H-636-AA</b> |                |          |                                                 |
| 1               | <b>0308607</b> | H-535    | 3/4" Adapter                                    |
| 1-4             | <b>3308788</b> | H-636-AA | Sweat Solder Kit for 3/4" Supply – Urinal       |
| 2               | —              | H-537    | Casing Tube for 3/4" Copper                     |

